



## POTENTIAL HAZARDOUS WASTE SITE IDENTIFICATION

REGION  
VI

SITE NUMBER

OKD007217748

NOTE: The initial identification of a potential site or incident should not be interpreted as a finding of illegal activity or confirmation that an actual health or environmental threat exists. All identified sites will be assessed under the EPA's Hazardous Waste Site Enforcement and Response System to determine if a hazardous waste problem actually exists.

## A. SITE NAME

Fibercast

## B. STREET (or other identifier)

25 S. Main

## C. CITY

Sand Springs

## D. STATE

OK

## E. ZIP CODE

74063

## F. COUNTY NAME

Tulsa

## G. OWNER/OPERATOR (if known)

## 1. NAME

Fibercast

## 2. TELEPHONE NUMBER

(918) 245-6651

## H. TYPE OF OWNERSHIP (if known)

☐ 1. FEDERAL ☐ 2. STATE ☐ 3. COUNTY ☐ 4. MUNICIPAL ☒ 5. PRIVATE ☐ 6. UNKNOWN

## I. SITE DESCRIPTION

This facility makes reinforced plastic pipe, fittings, and tanks. They also use thermo setting resin adhesives. There is believed to be a monitor well on the site.

J. HOW IDENTIFIED (i.e., citizen's complaints, OSHA citations, etc.) Request by EPA Region VI to investigate sites in vicinity of the Sand Springs NPL site.

## K. DATE IDENTIFIED

(mo., day, &amp; yr.)

5/2/88

## L. SUMMARY OF POTENTIAL OR KNOWN PROBLEM

This site is upgradient of the Sand Springs Petrochemical Complex National Priorities List (NPL) site. Chlorinated Hydrocarbons and other contaminants have been detected in the upgradient monitor wells of the NPL site. This site is to be investigated as part of an effort to identify sources of the contamination.

## M. PREPARER INFORMATION

## 1. NAME

Scott A. Thompson

## 2. TELEPHONE NUMBER

(405) 271-7168

## 3. DATE (mo., day, &amp; yr.)

2/16/89

9819510



AUG 20 1992

RECORDED